




LADDER INSPECTION


Halswell Exchange
 440 HALSWELL RD, HALSWELL
 SOUTH, CHRISTCHURCH CITY





Date of Inspection: 19/11/2015	Report Generated Date: 10/8/2015	Name of Inspector: James Ambrose
--------------------------------	----------------------------------	----------------------------------


Location Details		Material Details		Type Details		Photographs
Ladder No. Identifier :	HSL-01	Material :	Metal	Structure Type :	Ceiling Access	
Category :	B - Fixed	Height :	Medium			
Comments:						

Location Details		Material Details		Type Details		Photographs
Ladder No. Identifier :	HSL-05	Material :	Wood	Structure Type :	Stool	
Category :	A - Moveable	Height :	Small			
Comments:						

Location Details		Material Details		Type Details		Photographs
Ladder No. Identifier :	HSL-04	Material :	Wood	Structure Type :	A-Frame	
Category :	A - Moveable	Height :	Large			
Comments:						

Location Details		Material Details		Type Details		Photographs
Ladder No. Identifier :	HSL-02	Material :	Wood	Structure Type :	Travelling (MDF)	
Category :	C - Moveable on fixed path	Height :	Large			
Comments:						

Location Details		Material Details		Type Details		Photographs
Ladder No. Identifier :	HSL-03	Material :	Wood	Structure Type :	Travelling (MDF)	
Category :	C - Moveable on fixed path	Height :	Large			
Comments:						

Location Details		Material Details		Type Details		Photographs
Ladder No. Identifier :	HSL-06	Material :	Metal	Structure Type :	Ceiling Access	
Category :	B - Fixed	Height :	Medium			
Comments:						